

CORNERSTONE
Construction Services, Inc.

Solid Waste:

Resurfacing of Tipping Floor at the West Volusia Transfer Station – County of Volusia (2011-2016)

Phased Demolition, Removal and Replacement of Facility's Tipping Floors while maintain full functionality - Installation of High Strength Floor Topping, Removal & Replacement of Concrete Push Walls, and Installation of Steel Plating

Solid Waste Administration Building Pavement Rehabilitation – Orange County (2014)

Demolition, Removal & Replacement of Concrete Pavement, Mill & Repave Asphalt Parking Area, Crack Repair & Joint Repair

Solid Waste Administration Building Shop Floor Rehabilitation – Orange County (2013)

Demolition, Removal & Replacement of Shop Floor, Crack Repair

Sarno Transfer Station Floor Repair – Brevard County (2013)

Demolition & Removal of Tipping Floor, Replacement with 8,300 SF of High Strength Floor Topping, and Steel Nosing

McLeod Road Transfer Station Leachate Management System Modification – Orange County (2013)

Installation of 30,000 Gallon Double Containment Tank, including Pumps, Valves, Control Panel, Yard Piping, and Trench Drains

McLeod Road Transfer Station Tipping Floor Slab Replacement – Orange County (2012)

Demolition & Removal of Tipping Floors, and Replacement with High Strength Floor Topping

WCA - Gainesville Transfer Station – WCA of Florida (2012)

Emergency Repair – Demolition & Removal of Tipping Floors, Replacement with (8000 psi) High Strength Floor Topping, Removal & Replacement of Trench Drains.

Clay County Transfer Station – Waste Management (2010)

Phased Demolition & Removal of existing Tipping Floor, Concrete Reinforcing, and Replacement of Tipping Floor while maintain full functionality; Metal Building Repair and Structural Repairs to the Load Out Bays

McCormack Recycle Center – Orange County (2010)


Demolition, Removal & Replacement of facility's Tipping Floors, Steel Nosing, and Replacement of Concrete Push Walls

Ormond Beach Transfer Station – Waste Management Incorporated of Florida (2008)

Demolition & Removal of Tipping Floors, and Replacement with High Strength Floor Topping

McLeod Rd. Transfer Station – Orange County (2007)

Demolition & Removal of Tipping Floors, Replacement with High Strength Floor Topping, Removal & Replacement of Steel Edging, Repair Concrete Push Walls



CORNERSTONE
Construction Services, Inc.

Waste Management - Orlando Transfer Station – Orange County (2005)

Cast in Place Concrete Work

LB McLeod Paving – Orange County (2003-2004)

Demolition of Asphalt Paving, Concrete Paving & Subgrade; Replacement with new Subgrade and 4" S-1 Asphalt Paving over 10" Concrete Paving

Deland Transfer Station – County of Volusia (2003-2004)

Demolition & Removal of Tipping Floor, Replacement with High Strength Floor Topping, Removal & Replacement of Concrete Push Walls, and Installation of Steel Plating

Porter Transfer Station Tipping Floor Replacement – Orange County (2002)

Demolition & Removal of Tipping Floor, Replacement with 8000 SF High Strength Floor Topping

LB McLeod Transfer Station Tipping Floor – Orange County (2001)

Core Testing, Demolition & Removal of Tipping Floor, Subgrade Repair, and Installation of 8000 psi Micro-Silica Floor Topping